



104 Handy Revit Keyboard Shortcuts

Helping You Work
Smarter, Not Harder



Applications Menu			
Shortcut	Tools	Shortcut	Tools
Ctrl + C	Copy	Ctrl + S	Save
Ctrl + X	Cut	Ctrl + O	Open
Ctrl + V	Paste	Ctrl + N	New
Ctrl + Z	Undo	Ctrl + P	Print
Ctrl + Y	Redo		

Architecture: Build	
Shortcut	Tools
CL	Column
CM	Place a component
DR	Door
WA	Wall
WN	Window

Architecture: Model	
Shortcut	Tools
GP	Create Group
LI	Model Line

Architecture: Datum	
Shortcut	Tools
GR	Grid
LL	Level

Architecture: Room and Area	
Shortcut	Tools
RM	Room
RT	Tag Room

Architecture: Work Plane	
Shortcut	Tools
RP	Reference Plane

Annotate: Dimension	
Shortcut	Tools
DI	Aligned Dimension
EL	Spot Elevation

Annotate: Text	
Shortcut	Tools
FR	Find/Replace
TX	Text

Annotate: Detail	
Shortcut	Tools
DL	Detail Line

Annotate: Tag	
Shortcut	Tools
TG	Tag by Category

Collaborate: Synchronize	
Shortcut	Tools
ER	Editing Requests
RL/RW	Reload Latest

Function Keys	
Shortcut	Tools
F1	Display Revit Help
F7	Spelling
F8	Navigation Wheel
F10/Alt	Keytips
Spacebar	Flip or rotate 90 degrees selected elements
Tab	Cycles through snaps or chain of elements



Manage: Settings

Shortcut	Tools
SU	Sun and Shadow Settings
UN	Project Units

Modify: Clipboard

Shortcut	Tools
MA	Match Type Properties

Modify: View

Shortcut	Tools
EH	Hide in View: Hide Elements
EOD	Override Graphic in View
LW	Linework
VH	Hide in View: Hide Category

Modify: Geometry

Shortcut	Tools
CP	Cope: Apply Notching
PT	Paint
RC	Cope: Remove Notching
SF	Split Face

Modify: Modify

Shortcut	Tools	Shortcut	Tools
AA/AL	Align	OF	Offset
AR	Array	PN	Pin
CO/CC	Copy	RE	Scale
CS	Create Similar	RO	Rotate
DE	Delete	SL	Split Element
DM	Mirror – Draw Axis	TR	Trim/Extend to Corner
JJ	Join Geometry	UP	Unpin
MV	Move		
MM	Mirror – Pick Axis		

Snap

Shortcut	Tools	Shortcut	Tools
PC	Snap to Point Clouds	SP	Perpendicular
SC	Centers	SQ	Quadrants
SE	Endpoints	SR	Snap to Remote Objects
SI	Intersections	ST	Tangents
SM	Midpoints	SW	Work Plane Grid
SN	Nearest	SX	Points
SO	Snap Off	SZ	Close

View Control Bar

Shortcut	Tools	Shortcut	Tools
CX	Reveal Constraints	IC	Isolate Category
GD	Graphic Display Options	RH	Toggle Reveal Hidden Elements Mode
HC	Hide Category	RY	Ray Trace
HH	Hide Element	SD	Shaded
HI	Isolate Element	WF	Wireframe
HL	Hidden Line		
HR	Reset Temporary Hide/Isolate		

View: Graphics

Shortcut	Tools	Shortcut	Tools
RD	Render in Cloud	TL	Thin Lines
RG	Render Gallery	VG/VV	Visibility/Graphics
RR	Render		

View: Windows

Shortcut	Tools	Shortcut	Tools
KS	Keyboard shortcuts	WC	Cascade Windows
PP	Properties	WT	Tile Windows
TW	Tile Views		

Zoom

Shortcut	Tools	Shortcut	Tools
ZA	Zoom All to Fit	ZP/ZC	Previous Pan/Zoom
ZE/ZF/ZX	Zoom to Fit	ZR/ZZ	Zoom in Region
ZO/ZV	Zoom Out (2x)	ZS	Zoom Sheet Size

